


Quality Servomotor Repairs Ltd



Standard charge £355.00	Machine stub shaft for rotor (large rotor costs vary) £270.00	Reverse engineer and fabricate thermal feedback device £50.00
Complex Feedback interfaces and labour £200.00 - £300.00	Straighten shaft £120.00	Replace feedback From £340.00
Minor machining /manual mechanical corrections £40.00	Balance shaft (large/high speed costs vary) £50.00	Unwieldy motor Additional hours @ £40.00 p.h.
Minor electrical repairs £40.00	Machine bearing housing to fit insert (large housing costs vary) £150.00	Special/oversize bearings/oil seal Varies
Stone oil seal wear using lathe £30.00	Refurbish/repair brake, clean, hand-condition, set gap, build-rebuild to achieve maximum torque From £120.00	Re-tension bearings correctly using machined shims and tensioning washers From £50.00
Install shaft protector £50.00	Cleaning/Treatment of stator From £50.00	Replace chassis plug From £85.00
Re-sleeve shaft oil seal journal £120.00	Rewind stator From £500.00	Courier/packing From £30.00

** If additional work is necessary (machining, rewinding, brake replacement, feedback, etc), details and photos are provided.*

Each quote is built from the work and parts needed to effect a repair.

Quality Servomotor Repairs Ltd.

Company number: 7666886

Mob: 0751 803 0 803 <http://www.qualityservomotorrepairs.co.uk> sales@qsrl.co.uk Tel: 0161 4809030

Unit 26/C, Vernon Mill, Mersey Street, Stockport. SK1 2HX

VAT registration: 155 4894 76